Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/11011ME-0141 Work Order Type: Weatherization Audit Name: 11011ME-0141

| CLIENT II | NFOR | MAT | ION |
|------------------|------|-----|-----|
|------------------|------|-----|-----|

Client Name: 11011ME-0141 Address:

Philadelphia, TN Client ID: 11011ME-0141

Alt. Client ID: Loudon

CLIENT CONTACT INFORMATION

11011ME-0141 Applicant/Person of Record

<u>AGENCY INFORMATION</u>

Agency: Mid-East Community Action Agency Agency Phone: (865) 248-8661

Address: P. O. Box 790 Fax:

> Kingston, TN 37763 Email Address: mecaawap@mecaa.net

| Company Name & License Number: | |
|--------------------------------|--|
| Contractor's Signature: | |

<u>COMMENT</u>

SITE BUILT 1935 N GAS NO CERTIFIED FIRM RENOVATOR REQUIRED Charles Bolinger Ph# 931-260-6409

Client Name: 11011ME-0141 Client ID: 11011ME-0141 Alt. Client ID: Loudon

Work Order (Bid Form)

DOE Weatherization Assistant Work Order Name: WO/11011ME-0141 Version 8.5.0 Report Run On: 5/21/2010 Page 1 of 9

| Measure 1 Infil | tration Redctn | | | Componen | ts | | | Inspected |
|--|--|---------------------------|--------------------|---------------------------------|------------------------|--------------------|------------|-----------|
| basebo ceiling o master | seals, Pre= 3950 Target= ard around water heater of corners, living rm chimney bd, crown and baseboard at wall intersection. | closet, bas / needs bl | seboard ock off | ds in in bath , crack in the | room and e closet c | l at the of the | | |
| | | | | Estimated | · | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Miscellaneous Supplies | Infiltration Reduction | Each | 1 | | | | | |
| 2 Labor | LABOR | Each | 1 | | | | | |
| Other Detail | | | | | | 1 | | |
| | | | | | | | | |
| | | | | | |] | | |
| | | | Measur | e Sub Total: | |] | Sub Total: | |
| boo | stic Duct boot / Return c ot) /=8 Seal duct boots and t | | | | ne and pl | enum. | | Inspected |
| | | | | Estimated | | | Actual | |
| # Material / Labor1 Heating Equipment | Description / Comment MASTIC BOOTS | <i>Units</i> Each | Qty 8 | Unit Cost | Total | Qty | Unit Cost | Total |
| 2 Labor | Labor | Each | 1 | | | | | |
| Other Detail | | | | | | 1 | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | | | Sub Total: | |
| Field Notes: | | | | | | | | |
| | | | | | | | | |
| i i | | | | | | | | |

Client Name: 11011ME-0141 Client ID: 11011ME-0141 Alt. Client ID: Loudon DOE Weatherization Assistant Version 8.5.0 Page 2 of 9

| Measure 3 DWH Pipe Insulation | | | Componer | nts | | į | Inspected |
|---|----------------------|----------------|---------------------|-------|-----|------------------|-----------------|
| Comment FIRST 5' | | | | | | | |
| | | | Estimated | 1 | | Actual | |
| # Material / Labor Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation DHW Pipe Insulation | Each | 1 | | | | | |
| 2 Labor Labor | Each | 1 | | | | | |
| Other Detail | | | | | 1 | | |
| | | | | | | | |
| | | | | | | | |
| | | Measure | e Sub Total: | |] , | Sub Total: | |
| | | | | | | | |
| Measure 4 DWH Tank Insulation Comment | | | Componer | nts | | | Inspected |
| Comment | | | Estimated | d | | Actual | Inspected |
| Comment # Material / Labor Description / Comment | Units | Qty | - | | Qty | | Inspected Total |
| Comment | <i>Units</i> Each | | Estimated | d | Qty | Actual | |
| # Material / Labor Description / Comment 1 Hot Water DWH Tank Insulation Equipment | | Qty | Estimated | d | Qty | Actual | |
| # Material / Labor Description / Comment 1 Hot Water DWH Tank Insulation Equipment | Each | Qty 1 | Estimated | d | Qty | Actual | |
| # Material / Labor Description / Comment 1 Hot Water Equipment 2 Labor Labor | Each | Qty 1 | Estimated | d | Qty | Actual | |
| # Material / Labor Description / Comment 1 Hot Water Equipment 2 Labor Labor | Each | Qty 1 | Estimated | d | Qty | Actual | |
| # Material / Labor Description / Comment 1 Hot Water Equipment 2 Labor Labor | Each | Qty 1 1 | Estimated | d | | Actual | |
| # Material / Labor Description / Comment 1 Hot Water Equipment 2 Labor Labor | Each | Qty 1 1 | Estimated Unit Cost | d | | Actual Unit Cost | |

Report Run On: 5/21/2010

| Comment 208.5 S | I Insulation | | | Componen | <i>t</i> s W1 | | | Inspecte | |
|-----------------------------------|---|--------------|---------|------------------|---------------|-----|---------------------|----------|--|
| _ | QFT | | | | | | | | |
| | | | | Estimated | | | Actual | | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| 1 Insulation | Wall Insulation - Blown Cellulose - 2x4 Filled | SqFt | 208.5 | | | | | | |
| 2 Labor | LABOR | Each | 1 | | | | | | |
| Other Detail | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | Measure | e Sub Total: | | | Sub Total: | | |
| Field Notes: | | | | | | | | | |
| Measure 6 Wall Comment 225.5 S | | | | Componen | ts E1 | | | Inspecte | |
| | | | | Estimated | | | | | |
| # Material / Labor | Description / Comment | Units | 04- | | | | Actual | | |
| 1 Insulation | Description/ Comment | | Qty | Unit Cost | Total | Qty | Actual Unit Cost | Total | |
| | Wall Insulation - Blown Cellulose - 2x4 Filled | SqFt | 225.5 | Unit Cost | Total | Qty | | Total | |
| 2 Labor | Wall Insulation - Blown | SqFt Each | _ | Unit Cost | Total | Qty | | Total | |
| | Wall Insulation - Blown Cellulose - 2x4 Filled | | 225.5 | Unit Cost | Total | Qty | | Total | |
| 2 Labor | Wall Insulation - Blown Cellulose - 2x4 Filled | | 225.5 | Unit Cost | Total | Qty | | Total | |
| 2 Labor | Wall Insulation - Blown Cellulose - 2x4 Filled | | 225.5 | | Total | | Unit Cost | Total | |
| 2 Labor Other Detail | Wall Insulation - Blown Cellulose - 2x4 Filled | | 225.5 | Unit Cost | Total | | | Total | |
| 2 Labor | Wall Insulation - Blown Cellulose - 2x4 Filled | | 225.5 | | Total | | Unit Cost | Total | |

| | II Insulation | | | Componen | ts N1 | | | Inspected |
|---|--|----------------------|-----------|---------------------|-------|-----|------------------|-----------|
| Comment 183.5 S | SQFT | | | | | | | |
| | | | | Estimated | 1 | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation | Wall Insulation - Blown Cellulose - 2x4 Filled | SqFt | 183.5 | | | | | |
| 2 Labor | LABOR | Each | 1 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measure | e Sub Total: | | | Sub Total: | |
| Field Notes: | | | | | | | | |
| | | | | | | | | |
| | atherstrip Door (ea) D1 nyl or rubber style,,,, then | caulk. D- | | Componen | ts | | | Inspected |
| | | caulk. D- | | Componen Estimated | | | Actual | Inspected |
| Comment Use Vir | | caulk. D- | | - | | Qty | | Inspected |
| Comment Use Vir | nyl or rubber style,,,, then | | 1 | Estimated | 1 | Qty | Actual | |
| Comment Use Vir # Material / Labor 1 Doors | nyl or rubber style,,,, then | Units | Qty | Estimated | 1 | Qty | Actual | |
| Comment Use Vir # Material / Labor 1 Doors | nyl or rubber style,,,, then of the properties o | <i>Units</i> Each | 1 Qty 1 | Estimated | 1 | Qty | Actual | |
| Comment Use Vir # Material / Labor 1 Doors 2 Labor | nyl or rubber style,,,, then of the properties o | <i>Units</i> Each | 1 Qty 1 | Estimated | 1 | Qty | Actual | |
| Comment Use Vir # Material / Labor 1 Doors 2 Labor | nyl or rubber style,,,, then of the properties o | <i>Units</i> Each | 1 Qty 1 | Estimated | 1 | Qty | Actual | |
| Comment Use Vir # Material / Labor 1 Doors 2 Labor | nyl or rubber style,,,, then of the properties o | Units Each Each | 1 Qty 1 1 | Estimated | 1 | | Actual | |
| Comment Use Vir # Material / Labor 1 Doors 2 Labor | nyl or rubber style,,,, then of the properties o | Units Each Each | 1 Qty 1 1 | Estimated Unit Cost | 1 | | Actual Unit Cost | |
| # Material / Labor 1 Doors 2 Labor Other Detail | nyl or rubber style,,,, then of the properties o | Units Each Each | 1 Qty 1 1 | Estimated Unit Cost | 1 | | Actual Unit Cost | |

| Measure 9 W | /eatherstrip Door (ea) D2 | | | Componen | ts | | | Inspected |
|---|--|----------------------|------------------|--------------|-------|-----|------------|-----------------|
| Comment Use | Vinyl or rubber style,,,, then | caulk. D-2 | 2 | | | | | |
| | | | | Estimated | | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Doors | Weatherstrip Door | Each | 1 | | | | | |
| 2 Labor | Labor | Each | 1 | | | | | |
| Other Detail | | | | | | 1 | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measure | e Sub Total: | | | Sub Total: | |
| | | | | | | | | |
| Measure 10 W Comment 211.3 | | | | Componen | | | | Inspected |
| Comment 211.3 | 3 SQFT | | | Estimated | 1 | | Actual | |
| Comment 211.3 | 3 SQFT | <i>Units</i> SqFt | Qty 211.3 | - | | Qty | | Inspected Total |
| Comment 211.3 # Material / Labor 1 Insulation | Description / Comment Wall Insulation - Blown | | Qty | Estimated | 1 | Qty | Actual | |
| Comment 211.3 # Material / Labor 1 Insulation | Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled | SqFt | Qty 211.3 | Estimated | 1 | Qty | Actual | |
| Comment 211.3# Material / Labor1 Insulation2 Labor | Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled | SqFt | Qty 211.3 | Estimated | 1 | Qty | Actual | |
| Comment 211.3# Material / Labor1 Insulation2 Labor | Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled | SqFt | Qty 211.3 | Estimated | 1 | Qty | Actual | |
| Comment 211.3# Material / Labor1 Insulation2 Labor | Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled | SqFt Each | Qty 211.3 | Estimated | 1 | | Actual | |

| Measure 11 Wind | | Componer | Inspected | | | | | |
|---|--|----------------------|--------------|---------------------|----------|-----|------------------|-----------------|
| Comment 5 WIND | OWS CAULK | | | | | | | |
| | | | | Estimated | <i>H</i> | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Windows | Window Sealing | Each Window | 5 | | | | | |
| | Caulking Interior / Exterior | | | | | | | |
| 2 Labor | Labor | Each Window | 1 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measu | re Sub Total: | |] . | Sub Total: | |
| | | | | | | | | |
| Field Notes: | | | | | | | | |
| | Monitor is Needed | | | Componer | nts | | | Inspected |
| | Monitor is Needed | | | Componer | nts | | | Inspected |
| Measure 12 CO | Monitor is Needed | | | Componer | | | Actual | Inspected |
| Measure 12 CO I | Monitor is Needed Description / Comment | Units | Qty | - | | Qty | | Inspected Total |
| Measure 12 CO I | | <i>Units</i> Each | Qty 1 | Estimated | d | Qty | Actual | |
| Measure 12 CO I Comment # Material / Labor 1 Health and Safety | Description / Comment | | | Estimated | d | Qty | Actual | |
| Measure 12 CO I Comment # Material / Labor 1 Health and Safety Items | Description / Comment CO monitor | Each | 1 | Estimated | d | Qty | Actual | |
| Measure 12 CO II Comment # Material / Labor 1 Health and Safety Items 2 Labor | Description / Comment CO monitor | Each | 1 | Estimated | d | Qty | Actual | |
| Measure 12 CO II Comment # Material / Labor 1 Health and Safety Items 2 Labor | Description / Comment CO monitor | Each | 1 | Estimated | d | Qty | Actual | |
| Measure 12 CO II Comment # Material / Labor 1 Health and Safety Items 2 Labor | Description / Comment CO monitor | Each | 1 | Estimated | d | | Actual | |
| Measure 12 CO II Comment # Material / Labor 1 Health and Safety Items 2 Labor | Description / Comment CO monitor | Each | 1 | Estimated Unit Cost | d | | Actual Unit Cost | |
| Measure 12 CO II Comment # Material / Labor 1 Health and Safety Items 2 Labor Other Detail | Description / Comment CO monitor | Each | 1 | Estimated Unit Cost | d | | Actual Unit Cost | |

Report Run On: 5/21/2010

| | Measure 13 Pres | sureRelief Piping Need | ded | | Componen | ts | | ı | nspected |
|---|-------------------------|---|-------|---------|---------------|-----------|-------|------------------|----------|
| C | Comment | | | | | | | | |
| | | | | | Estimated | <u> </u> | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Health and Safety Items | Pressure relief piping | Each | 1 | | | | | |
| 2 | Labor | Labor | Each | 1 | | | | | |
| (| Other Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | |
| | | | | | | | | | |
| | | or Barrier Needed sement/Crawlspace) | | | Componen | ts | | ı | nspected |
| C | Comment Use 6 m | nil plastic. 927 SF. May n tend up walls 6" , tape o | | to cove | er all due to | low clear | ance, | | |
| | | | | | Estimated | <u> </u> | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Health and Safety Items | Basement / crawlspace vapor barrier | SqFt | 927 | | | | | |
| 2 | | vapor barrier | | | | | | | |
| | Labor | Labor | Each | 1 | | | | | |
| | Labor Other Detail | · | Each | 1 | | | | | |
| | | · | Each | 1 | | | | | |
| | | · | Each | 1 | | | | | |
| | | · | | | e Sub Total: | | | Sub Total: | |

Report Run On: 5/21/2010

| Measure 15 Attic access (ea) | | | | Componen | ı | Inspected | | |
|------------------------------|---------------------------------|--------|-----------|------------------|-------|-----------|------------------|-------|
| Comment | Block hole and Insulate lid. (R | 30) | | | | | | |
| | | | Estimated | | | | | |
| # Material / | Labor Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Other | Attic Access | Each | 1 | | | | | |
| 2 Labor | Labor | Each | 1 | | | | | |
| Other Detail | 1 | | 1 | | | 1 | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | |] ; | Sub Total: | |
| Field Note | s: | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | Work O | rder Gra | and Total: | | Gran | d Total: | |